

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

*C/SF*  
**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other ☐ P&A  
2. NAME OF OPERATOR  
Yates Petroleum Corporation  
3. ADDRESS OF OPERATOR  
207 South 4th St., Artesia, NM 88210  
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 660' FSL & 660' FEL, Sec. 27-6S-25E  
AT SURFACE:  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

- |                      |                                     |                                     |
|----------------------|-------------------------------------|-------------------------------------|
| TEST WATER SHUT-OFF  | <input type="checkbox"/>            | <input type="checkbox"/>            |
| FRACTURE TREAT       | <input type="checkbox"/>            | <input type="checkbox"/>            |
| SHOOT OR ACIDIZE     | <input type="checkbox"/>            | <input type="checkbox"/>            |
| REPAIR WELL          | <input type="checkbox"/>            | <input type="checkbox"/>            |
| PULL OR ALTER CASING | <input type="checkbox"/>            | <input type="checkbox"/>            |
| MULTIPLE COMPLETE    | <input type="checkbox"/>            | <input type="checkbox"/>            |
| CHANGE ZONES         | <input type="checkbox"/>            | <input type="checkbox"/>            |
| ABANDON*             | <input checked="" type="checkbox"/> | <input type="checkbox"/>            |
| (other) Spud well    | <input type="checkbox"/>            | <input checked="" type="checkbox"/> |

5. LEASE  
NM 10588  
6. IF INDIAN, ALLOTTEE OR TRIBE NAME  
7. UNIT AGREEMENT NAME  
8. FARM OR LEASE NAME  
George QJ Federal  
9. WELL NO.  
2  
10. FIELD OR WILDCAT NAME  
Und. Abo Pecos Deep No.  
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Unit P, Sec. 27-6S-25E  
12. COUNTY OR PARISH  
Chaves  
13. STATE  
NM  
14. API NO.  
15. ELEVATIONS (SHOW DF, KDB, AND WD)  
3758' GR

RECEIVED

FEB 24 1982

O. C. D.

ARTESIA OFFICE


(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Ran 40' of 20" conductor pipe. Spudded a 12-1/4" hole at 11:45 AM 1-19-82. Lost circulation at 853'. Fished for drill collars and bit. Ran free point. Pipe stuck at 750'. Backed off at 730'. RIH and jar on fish with no success.

Verbal approval to fill the hole with cement for plugging and skidding obtained from Mr. Roger Chapman, USGS, Roswell on January 25, 1982. Regulation abandonment marker will be installed.

An application for permit to drill the George QJ Federal #2-Y will be submitted.



Subsurface Safety Valve: Manu. and Type

Set @ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Engineering Secty. 27-82

APPROVED

(This space for Federal or State office use)

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

FEB 1 1982

FOR

JAMES A. GILLHAM  
DISTRICT SUPERVISOR

\*See Instructions on Reverse Side