

NM OIL CONS. COMMISSION
Drawer DD
Artesia, NM 88210

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

RECEIVED BY
NOV 09 1984
Form Approved
Budget Bureau No. 42-R1424
O. C. D.
ARTESIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☐ other Dry Hole
2. NAME OF OPERATOR
HUSKY OIL COMPANY ✓
3. ADDRESS OF OPERATOR
6060 So. Willow Drive; Englewood, CO 80111
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 670' FNL & 660' FWL NW $\frac{1}{4}$ NW $\frac{1}{4}$
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

5. LEASE
N M 16316
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Bitter Lake Federal
9. WELL NO.
2-Y (Re-drill of Well #2)
10. FIELD OR WILDCAT NAME
Wildcat - *Also*
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Section 24; T8S; R24E
12. COUNTY OR PARISH
Chaves
13. STATE
New Mexico
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3572'

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF	<input type="checkbox"/>	
FRACTURE TREAT	<input type="checkbox"/>	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>	<input type="checkbox"/>
(other) Rehabilitation of Location		

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Reserve pits leveled and location rehabilitated by Sweatt Construction Company of Roswell, New Mexico.

Location is ready for your inspection.


Subsurface Safety Valve: Manu. and Type _____

18. I hereby certify that the foregoing is true and correct

SIGNED Vera Chandler Associate Environmental Analyst DATE March 27, 1984
APPROVED PETER W. CHASTER TITLE Analyst 303/850-1462
(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

NOV 8 1984



Post FD-2
11-23-84
P & A