

sf/file

UNITED STATES Artesia, NM 88210
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

5. LEASE
LC-067811A
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Dale - Federal
9. WELL NO.
No. 10 Dale - Federal
10. FIELD OR WILDCAT NAME
Leslie Spring, San Andres
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 26, T.7S, R.26E.
12. COUNTY OR PARISH
Chaves
13. STATE
N.M.
14. API NO.
3833.8 GL
15. ELEVATIONS (SHOW OF, KDB, AND WD)

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐ JUL 1 1982

2. NAME OF OPERATOR ☒ O. C. D.
Berge Exploration, Inc. ARTESIA, OFFICE

3. ADDRESS OF OPERATOR
7100 N. Broadway, 2-L, Denver, CO 80221

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 990' FEL X 1650' FSL
AT TOP PROD. INTERVAL: (as above)
AT TOTAL DEPTH: (as above)


16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF	<input type="checkbox"/>		<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>		<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>		<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>		<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>		<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>		<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>		<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>		<input type="checkbox"/>
(other) Run production casing	<input type="checkbox"/>		<input type="checkbox"/>

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Ran 47 joints 4 1/2 in., 10.5#, J-55 csg. to 1996' GL w/205 sax, class C, 2% CCI cement. Plug down 5:15 pm 6/10/82



OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Verne P. Barry TITLE Vice President DATE _____

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

*See Instructions on Reverse Side

JUN 30 1982
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO