

RECEIVED

NM OIL CONS. COMMISSION

Drawer DD

Artesia, NM 88210

NOV 16 1982

Form 9-331
Dec. 1973Form Approved.
Budget Bureau No. 42-R1424UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ well gas ☐ well other ☐
2. NAME OF OPERATOR
Berge Exploration, Inc.
3. ADDRESS OF OPERATOR
7100 N. Broadway, Ste. 2-L, Denver, CO 80221
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 330' FWL x 2970' FSL
AT TOP PROD. INTERVAL: as above
AT TOTAL DEPTH: as above

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

- TEST WATER SHUT-OFF ☐
- FRACTURE TREAT ☐
- SHOOT OR ACIDIZE ☐
- REPAIR WELL ☐
- PULL OR ALTER CASING ☐
- MULTIPLE COMPLETE ☐
- CHANGE ZONES ☐
- ABANDON* ☐
- (other) ☐

- ☐
- ☒
- ☒
- ☐
- ☐
- ☐
- ☐
- ☐

5. LEASE
NM-43714
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Date Federal
9. WELL NO.
No. 1 Worley-Federal
10. FIELD OR WILDCAT NAME
Leslie Spring, San Andres
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 25, T7S, R26E
12. COUNTY OR PARISH
Chaves
13. STATE
New Mexico
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3856.4 GL

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

6-10-82: Perf @ 1528-1536 w/16 shots, @ 1762-1766 w/8 shots,
@1770-1782 w/12 shots, @ 1838-1840 w/2 shots, @.40".

6-21-82: Acidized w/2750 gal 15% DS-30

7-09-82: TOP

7-20-82: Perf w/4 SPF @ 1528-1536, 1762-1766, 1770-1782
Stress Frac @ 1528-1536, 1762-1766, 1770-1782.

7-21-82: TOP

8-05-82: SI

8-16-82: Perf w/4 SPF @ 1521-1527, 1539-1541, 1544, 1549-1551, 1555-1563

9-13-82: TOP

10-9-82: SI, end of test period.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Holly L. Morris TITLE GeologistDATE Nov. 10 1982APPROVED BY (ORIG. SGD.) DAVID R. GLASS

CONDITIONS OF APPROVAL IF ANY

NOV 15 1982

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side

NOV 15 1982