MARTIN YATES, III 1912 - 1985 FRANK W. YATES 1936 - 1986



105 SOUTH FOURTH STREET ARTESIA, NEW MEXICO 88210 TELEPHONE (505) 748-1471

November 3, 1988

S. P. YATES CHAIRMAN OF THE BOARD JOHN A. YATES PRESIDENT PEYTON YATES EXECUTIVE VICE PRESIDENT RANDY G. PATTERSON SECRETARY DENNIS G. KINSEY TREASURER

RECENTED

NOV 07 '88

O. C. D. ARTESIA, OFFICE

State of New Mexico Energy, Minerals & Natural Resources Dept. Oil Conservation Division P.O. Drawer DD Artesia, New Mexico 88210

Re: Skinny "QO" State #3 Unit M, Sec. 16-T7S-R25E Chaves County, New Mexico

ATTENTION: Mr. Mike Williams

Dear Mike:

The above referenced well was plugged back (copy of C-103 attached), however the well has not been plugged and abandoned and has not been completed.

If additional information is needed, please let me know.

Yours truly,

UT Juanita Goodlett

Production Supervisor

Encl.

STATE OF NEW MEXICO	C						
RAGY AND MINERALS DEPAR			ал. <u>та</u>				
	OIL	CONSERVA	THEREDISION		· · ·		
DISTRIBUTION	P. O. BOX 2088				orm C-103 evised 10-1-7		
SANTA PE	SA SA	SANTA FE, NEW MEXICO 87501			אני בי באלי בי בי בי	2413EQ 10-1-7	
FILE					icate Type of L	euso	
U.S.O.S.			NOV 07 '88	Sta	• X	Fee	
LAND OFFICE					• Oil & Gus Lee	ase No.	
OPERATOR		C , C , C ,				LG-4333	
DO NOT USE THIS FORM FO USE "APP	NDRY NOTICES AN A PAOPOSALS TO BAILL OR LICATION FOR PERMIT	D REPORTS ON	ALK TO A DIFFERENT RESERVOIR.	////	Agreement Nam	ne	
	0THE n -				and averables		
ame of Operator					8. Farm or Lease Name Skinny QO State		
Yates Petroleum Corporation V							
ddress of Operator					9. Well No.		
207 South 4th St., Artesia, NM 88210							
cation of Well				10. Field and Pool, or Wildcat Und. San Andres			
M	660	South	LINE AND 660	LET PROM			
JIT LETTER						///////	
West Line,	16	TOWNSHIP 65	RANGE 25E	нмрм.			
					7111111	<i>+++++++</i> +	
11111111111111111111111111111111111111				12. Co	uniy N		
		3929.4' GH	ર	Cha	ves 💦	1111111	
		To Indianto N	lature of Notice, Repor	r or Other Da			
		x to indicate N					
NOTICE	F INTENTION TO:		50851	EQUENT REPO	DRT OF:		
				()		Г	
DAM REMEDIAL WORK	PL	UG AND ABANDON	REMEDIAL WORK	Ц	ALTERING C		
GRARILY ABANDON			COMMENCE DRILLING OPHS.		PLUG AND A	BANDONMENT	
OR ALTER CASING	CH	ANGE PLANS	CASING TEST AND CEMENT JOB Plugback to	L_ test San A	ndres	X	
		·	OTHER			L^	
THE R							
			<u> </u>				

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged back well as follows:

Plug #1: 50 sacks Class "C" Neat plug from 3750-3650'. PD 8:30 PM 6-7-82 Plug #2: 50 sacks Class "C" Neat plug from 1750-1650'. PD 9:20 PM 6-7-82

Ran 26 joints of 4-1/2" 10.5# J-55 casing at 1600'. 1-regular guide shoe at 1600'. Float collar at 1558'. Used 250 gallons of mud flush ahead of cement. Cemented w/ 300 sacks 50/50 Poz with 6# salt. Compressive strength of cement - 1050 psi in 12 hours. PD 2:10 PM 6-8-82. Bumped plug to 1000 psi, released pressure and float held okay. Cement circulated 25 sacks to pit. WOC. WIH and perforated 1397-1407' w/l1 .50" holes. Spot acid across perforations 1397-1407' w/500 gallons 7½% NE acid and 10 balls.

Alwady have this erpy

3. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

ILAND Ara ante Dundlet	Engineering Secretary	DATE