STATE OF NEW MEXICO				
ENERGY AND MINERALS DEPARTMENT	L CONSERVATION	DIVISI		
DISTRIBUTION	P. O. BOX 2088		Form C-103	
SANTA FE	SANTA FE, NEW MEXI	CO 87800 1 0 1000	Revised 10-	1-78
TILE		CO CHPR 1 2 1982	Sa. Indicate Type of Lease	
U.S.G.S.			State State Fee	
LAND OFFICE		O. C. D.		ــــــــــــــــــــــــــــــــــــــ
OPERATOR /		ARTESIA, OFFICE	5, State Off & Gas Lease No.	
SUNDRY NOT IL	CES AND REPORTS ON WELLS	, DIFFERENT RESERVOIR, ALS.1		M
			7, Unit Agreement Hanie	
hame of Operator			8. Farm or Leuse Name	
Yates Petroleum Corporation /			Sacra SA	
Address of Operator			9. Well No.	
207 South 4th St., Artesia, NM 88210			2	
Location of Well			10. Field and Pool, or Wildcat	
UNIT LETTER P 660	star months South	AND 660 FEET FROM	Und. Pecos Slope Abo	)
UNIT COULD			<u>AIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII</u>	$\mathcal{T}\mathcal{I}$
THE East LINE, SECTION 23	6S	25E		///
the tine, section		NCE		11)
IS. Elevation (Show whether DF, RT, GR, etc.)			12. County	111
			Chaves	$\overline{\eta}$
Check Appropri	iate Box To Indicate Nature o	of Notice, Report or Ot	her Data	
NOTICE OF INTENTIC	DN TO:	SUBSEQUEN	T REPORT OF:	
RFORM REMEDIAL WORK	PLUG AND ABANDON REMEDI		ALTERING CASING	
	COMMEN	CE DRILLING OPHS.	PLUG AND ABANDONMENT	
LL OR ALTER CASING	CHANGE PLANS CASING	TEST AND CEMENT JOB		
	ОТН			
				· •
UIRER				
2. Describe Proposed or Completed Operations ( work) SEE RULE 1103.	Clearly state all pertinent details, and	give pertinent dates, including	; estimated date of starting any propo	osed

Spudded a 14-3/4" hole at 6:00 PM 4-3-82. Set 40' of 20" conductor pipe. Ran 22 joints of 10-3/4" 40.5# J-55 casing set at 880'. 1-Texas Pattern guide shoe at 880'. Insert float at 840'. Cemented w/600 sacks Pacesetter Lite "C" 3% CaCl<sub>2</sub>. Tailed in w/400 sacks Class "C" 2% CaCl<sub>2</sub>. Compressive strength of cement - 1250 psi in 12 hours. PD 10:00 AM 4-5-82. Bumped plug to 750 psi, released pressure and float held okay. WOC. Drilled out 4:00 AM 4-6-82. WOC 18 hours. Nippled up and tested to 1000 psi, okay. Reduced hole to 9-7/8". Drilled plug and resumed drilling. Circ 25 5x5

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

$\mathcal{L}$	· ·	
Allen Ta Don dlott	Engineering Secretary	4-9-82
	•	

OIL AND GAS INSPECTOR

APR 261982

NDITIONS OF APPROVAL, IF ANY: