

ALBUQUERQUE, NM 88210
UNITED STATES

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well ☐ gas ☐ well ☐ other ☒ Junk & Abandon

2. NAME OF OPERATOR

Berge Exploration, Inc.

3. ADDRESS OF OPERATOR

Denver,

7100 N. Broadway, Ste. 2-L, CO 80221

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1980' FSL & 660' FWL

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☒

(other)

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☐
☒

RECEIVED
MAY 10 1982

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Junked & abandoned above well on 5/3/82 per verbal approval as follows:

TD 4301'. Spot 100 sx Class "C" plug + 2% CaCl₂ from 705' to 420'. WOC. TIH w/DP. Tagged plug @ 420'. Pull up & spot 10 sx Class "C" + 2% CaCl₂ from 60' to surface. LD DP & DC. Install Dry Hole Marker.

Rig released @ 12:00 AM 5/3/82

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Agent


DATE May 5, 1982

APPROVED (This space for Federal or State office use)
(ORIG. SGD.) DAVID R. GLASS

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

OCT 6 1983



*See Instructions on Reverse Side

Post FD-2
5-28-82
P4A

RECEIVED BY
OCT 06 1983
O. C. D.
ARTESIA, OFFICE