1. oil

Form Approved. Budget Bureau No. 42-R1424

UNITED STATES

Drawer DD Artesia, MA

85210 LEASE

	DEPARTMENT	OF	THE	INTERIOR
C/SF	GEOLOG	ICAL	. SUF	RVEY

	NM	39127	7	
6. IF INDI	AN. ALI	OTTEE	OR TRIBE	NAME

C/.	SF	
-----	----	--

MAR 1 2 1982 7. UNIT AGREEMENT NAME

SUNDRY NOTICES AND REPORTS ON WELLS

8. FARM OR LEASE NAME Doris RI Federal

O. C. D. ARTESIA, OFFICE

RECEIVED

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

9. WELL NO.

well well 2. NAME OF OPERATOR

Yates Petroleum Corporation /

 \mathbf{x}

10. FIELD OR WILDCAT NAME Undesignated Abo

3. ADDRESS OF OPERATOR

gas

207 South 4th St., Artesia, NM 88210

other

11. SEC., T., R., M., OR BLK. AND SURVEY OR

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 990' FNL & 1650 FWL, Sec. 27-5S-25E AT SURFACE:

Unit C, Sec. 27-5S-25E 12. COUNTY OR PARISH 13. STATE

AT TOP PROD. INTERVAL: AT TOTAL DEPTH:

14. API NO.

Chaves

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

15. ELEVATIONS (SHOW DF, KDB, AND WD) 3745.7' GR

change on Form 9-330.)

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL

PULL OR ALTER CASING MULTIPLE COMPLETE

CHANGE ZONES ABANDON*

(other)

(NOTE: Report results of multiple completion or zone

SUBSEQUENT REPORT OF:

OIL & GAS U.S. GEOLOGICAL SURVEY ROSWELL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Set 30' of 20" conductor pipe. Spudded a 12-1/4" hole at 11:00 PM 2-14-82. Ran 23 joints of 8-5/8" 24# J-55 ST&C casing set at 916'. 1-notched guide shoe at 916'. Auto-fill float at 887'. Cemented w/500 sacks Howco Lite 2% CaCl₂ & 2% flocele. Tailed in w/200 sacks Howco "C" 2% CaCl₂. PD 8:30 AM 2-16-82. Bumped plug to 850 psi, released pressure and float held okay. Cement circulated 50 sacks to pit. WOC. Drilled out 3:30 AM 2-17-82. WOC 19 hours. Nippled up and tested to 1000 psi, okay. Reduced hole to 6-1/4". Drilled plug and resumed drilling.

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct

(///(TITLE Engineering Secty DATE 2-22-82

(This space for Federal or State office use)

APPROVED BY ACCEPTED FOR RECORD CONDITIONS OR GEREVAL, IE HAPMAN

2 1982 MAR

See Instructions on Reverse Side

U.S. GEOLOGICAL SURVEY

ROSWELL, NEW MEXICO