

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other
2. NAME OF OPERATOR
Yates Petroleum Corporation /
3. ADDRESS OF OPERATOR
207 South 4th St., Artesia, NM 88210
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 1980 FNL & 660 FWL, Sec. 30-6S-26E
AT SURFACE:
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>
FRACTURE TREAT	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
MULTIPLE COMPLETE	<input type="checkbox"/>
CHANGE ZONES	<input type="checkbox"/>
ABANDON*	<input type="checkbox"/>
(other)	<input type="checkbox"/>

SUBSEQUENT REPORT OF:

[illegible]

RECEIVED
(NOTE: Re
ch.)
MAR 5 1982

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Verbal permission was obtained from Mr. Jim Gillham, USGS, Roswell 2-25-82 by Mr. Ray Stall, Yates Petroleum Corporation, to change casing point from 950' to 900'.

Spudded a 14-3/4" hole at 11:30 AM 2-23-82. Ran 22 joints of 10-3/4" 40.5# ST&C casing set at 894'. 1-Texas Pattern guide shoe at 894'. Insert auto-fill float at 854'. Cemented w/400 sacks Class "C" Pacesetter Lite and 1/4# celloseal. Tailed in w/300 sacks Class "C" 2% CaCl₂. PD 7:30 PM 2-25-82. Bumped plug to 750 psi, released pressure and float held okay. Circulated 50 sacks to pit. WOC. Drilled out 1:30 PM 2-26-82. WOC 18 hours. Nippled up and tested to 1000 psi, okay. Reduced hole to 9-7/8". Drilled plug and resumed drilling.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED _____ TITLE Engineering Secty DATE 3-4-82

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE _____

ACCEPTED FOR RECORD

MAR 10 1982

U.S. GEOLOGICAL SURVEY
ROSWell, NEW MEXICO