

OCT 27 1982

UNITED STATES DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

Drawer DD  
Artesia NM 88210

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other ☐
2. NAME OF OPERATOR  
Yates Petroleum Corporation
3. ADDRESS OF OPERATOR  
207 South 4th St., Artesia, NM 88210
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)  
AT SURFACE: 1980 FNL & 660 FWL  
AT TOP PROD. INTERVAL:  
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

- | REQUEST FOR APPROVAL TO: |                          | SUBSEQUENT REPORT OF: |                                     |
|--------------------------|--------------------------|-----------------------|-------------------------------------|
| TEST WATER SHUT-OFF      | <input type="checkbox"/> |                       | <input checked="" type="checkbox"/> |
| FRACTURE TREAT           | <input type="checkbox"/> |                       | <input type="checkbox"/>            |
| SHOOT OR ACIDIZE         | <input type="checkbox"/> |                       | <input type="checkbox"/>            |
| REPAIR WELL              | <input type="checkbox"/> |                       | <input type="checkbox"/>            |
| PULL OR ALTER CASING     | <input type="checkbox"/> |                       | <input type="checkbox"/>            |
| MULTIPLE COMPLETE        | <input type="checkbox"/> |                       | <input type="checkbox"/>            |
| CHANGE ZONES             | <input type="checkbox"/> |                       | <input type="checkbox"/>            |
| ABANDON*                 | <input type="checkbox"/> |                       | <input type="checkbox"/>            |
| (other)                  | <input type="checkbox"/> |                       | <input type="checkbox"/>            |

5. LEASE  
NM 9539
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME  
Williamson LC Federal
9. WELL NO.  
5
10. FIELD OR WILDCAT NAME  
Pecos Slope Abo
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA  
Unit E, Sec. 9-T8S-R25E
12. COUNTY OR PARISH  
Chaves
13. STATE  
NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)  
3606.6' GR

RECEIVED

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

OCT 25 1982

OIL & GAS  
MINERALS MGMT. SERVICE  
ROSWELL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Spudded a 14-3/4" hole at 2:50 PM 10-7-82. Set 40' of 20" conductor pipe. Ran 24 joints of 10-3/4" 40.5# J-55 casing set at 958'. 1-Texas Pattern notched guide shoe set at 958'. Regular insert float set at 918'. Cemented w/100 sacks Thixset, 1/2# flocele. Tailed in w/250 sacks Class "C" with 2% CaCl<sub>2</sub>. Compressive strength of cement - 1250 psi in 12 hours. PD 12:45 AM 10-10-82. Bumped plug to 1000 psi, released pressure and float held okay. Cement did not circulate. WOC 6 hours. Ran Temperature Survey and found top of cement at 150'. Ran 1". Tagged cement at 150'. Spotted 250 sacks Class "C" with 2% CaCl<sub>2</sub>. PD 8:00 AM 10-10-82. Cement circulated 20 sacks to pit. WOC. Drilled out 6:45 PM 10-10-82. WOC 18 hours. Nipped up and tested to 1000 psi, okay. Reduced hole to 7-7/8". Drilled plug and resumed drilling.

Subsurface Safety Valve: Manu. and Type \_\_\_\_\_ Set @ \_\_\_\_\_ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED \_\_\_\_\_ TITLE Engineering Secty DATE 10-21-82

APPROVED BY  
CONDITIONS OF

ACCEPTED FOR RECORD  
(This space for Federal or State office use)  
(ORIG. SGD.) DAVID R. GLASS

OCT 26 1982

U.S. GEOLOGICAL SURVEY  
ROSWELL, NEW MEXICO

\*See Instructions on Reverse Side