

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

MINERAL COMMISSION
Dr. J. D. D.
Artesia, NM 88210

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well ☐ gas ☒ well ☐ other

2. NAME OF OPERATOR

MESA PETROLEUM CO. ✓

3. ADDRESS OF OPERATOR

1000 VAUGHN BUILDING/MIDLAND TX 79701-4493

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

990' FSL & 1883' FWL

AT SURFACE:

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH: SAME

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) 8 5/8" CSG & CMT

5. LEASE
NM 20337

6. IF INDIAN, ALLOTTEE OR TRIBE NAME RECEIVED

7. UNIT AGREEMENT NAME

MAY - 6 1982

8. FARM OR LEASE NAME
BEDFORD FEDERAL

O. C. D.

9. WELL NO.
3

ARTESIA, OFFICE

10. FIELD OR WILDCAT NAME
PECOS SLOPE ABO

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

SEC 31, T6S, R25E

12. COUNTY OR PARISH
CHAVES

13. STATE
NEW MEXICO

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3950.8' GR

(NOTE: Report results of multiple completion or change of Form 9-330)

RECEIVED
APR 01 1982

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Drilled 12 1/2" hole to 1735' and ran 42 jts 8 5/8", 24#, K-55 casing set at 1735'. Cemented with 700 sx Thixalite + 4% CaCl + 1/4#/sx flocele and tailed in with 300 sxs Class "C" + 2% CaCl. Plug down at 11:30 AM, 3-25-82. Cement did not circulate. Ran temperature survey -- TOC at 1280'. Set four plugs with a total of 750 sxs Thixset + 4% CaCl to circulate cement. Tested BOP's and casing to 600 psi - OK. Reduced hole to 7 7/8" and drilled ahead on 3-27-82. WOC total of 49 hours.

ACCEPTED FOR RECORD

XC: MMS (6), TLS, CEN RCDS, ACCTG, MEC, ROSWELL REM. FILE, (PARTNERS)

Subsurface Safety Valve: Manu. and Type

Set @ Ft.

18. I hereby certify that the foregoing is true and correct

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

SIGNED R. E. Madsen

TITLE REGULATORY COORDINATOR 3-29-81

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

RECEIVED

APR 30 1982

O.C.D.
HOUSING DIVISION