

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

C/SF
SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other ☐

2. NAME OF OPERATOR

Yates Petroleum Corporation

3. ADDRESS OF OPERATOR

207 South 4th St., Artesia, NM 88210

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) 1980 FSL & FWL, Sec. 35-5S-24E

AT SURFACE:

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐


MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) ☐

SUBSEQUENT REPORT OF:



OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWell, NEW MEXICO

5. LEASE

NM 30388

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

RECEIVED

8. FARM OR LEASE NAME
Kisner TB Federal

MAY - 3 1982

9. WELL NO.

1

O. C. D.

ARTESIA, OFFICE

10. FIELD OR WILDCAT NAME

Pecos Slope Abo

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Unit K, Sec. 35-T5S-R24E

12. COUNTY OR PARISH

Chaves

13. STATE

NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3952' GR

NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded a 12-1/4" hole at 8:00 AM 4-4-82. Set 40' of 20" conductor pipe. Ran 22 joints of 8-5/8" 24# casing set at 863'. 1-Texas Pattern guide shoe set at 863'. Insert float set 823'. Cemented w/400 sx Pacesetter Lite, 3% CaCl. Tailed in w/300 sx Class "C" w/2% CaCl. PD 12:15 AM 4-6-82. Bumped plug to 750 psi, released pressure & float held okay. Circulated 50 sx to pit. WOC. Drilled out at 6:15 PM 4-6-82. WOC 18 hours. Nippled up & tested to 1000 psi okay. Reduced hole to 7-7/8". Drilled plug & resumed drilling.

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct

SIGNED

Andrés González

TITLE

Engineering Section

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

