Form 9-331 Drawer Dec. 1973 Drawer Artonited States States DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	Form Approved. Budget Bureau No. 42-R1424 5. LEASE NM 2351 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drift or to deepen RECEIVED o a different reservoir. Use Form 9-331-C for such proposals.) 1. oil gas well other OCT 5, 1982 2. NAME OF OPERATOR Yates Petroleum Corporation O.VC. D. 3. ADDRESS OF OPERATOR ARTESIA, OFFICE 207 South 4th St., Artesia, NM 88210 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 660 FSL & 1980 FWL, Sec. 34-7S-25E AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	 7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME Federal HY 9. WELL NO. 4 10. FIELD OR WILDCAT NAME Pecos Slope Abo 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Unit_N, Sec. 34-T7S-R25E 12. COUNTY OR PARISH 13. STATE Chaves
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF X FRACTURE TREAT X SHOOT OR ACIDIZE X PULL OR ALTER CASING X MULTIPLE COMPLETE X CHANGE ZONES X ABANDON* X	 14. API NO. 15. ELEVATIONS (SHOW DF, KDB, AND WD) 3554.3' GR (NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded a 14-3/4" hole 6:00 PM 7-13-82. Set 40' of 20" conductor pipe. Ran 19 joints of 10-3/4" 40.5# J-55 casing set 767'. 1-Texas Pattern notched guide shoe set 767'. Regular insert float set 727'. Cemented w/200 sacks Thixolite, 1/4# celloseal, 3% CaCl2, 300 sacks Pacesetter Lite, 3% CaCl2. Tailed in w/300 sacks Class "C" with 2% CaCl2. Compressive strength of cement - 1050 psi in 12 hours. PD 9:07 AM 7-15-82. Bumped plug to 1000 psi, released pressure and float held okay. WOC. Cement did not circulate. Ran Temperature Survey and found top of cement at 425'. WOC 6 hours. Ran 1". Tagged cement at 170'. Cemented w/285 sacks Class "C" with 3% CaCl2. PD 5:45 PM 7-15-82. WOC 45 minutes. Ran 1". Tagged cement at 150'. Cemented w/175 sacks Class "C" with 3% CaCl2. Cement circulated 15 sacks to pit. WOC. Drilled out 3:00 AM 7-16-82. WOC 18 hours. Nippled up and tested to 1000 psi, okay. Reduced hole to 9-7/8". Drilled plug and resumed drilling. Subsurface Safety Valve: Manu. and Type ____

----- Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

Dadlet TITLE Engineering Secty DATE 7-21-82 SIGNED 1 ACCEPTED FOR BECORDis space for Federal or State office use) APPROVED BY DATE CONDITIONS OF APPROVAL, OCT 4 1982 U.S. GEOLOGICAL SURVEY Instructions on Reverse Side OIL & GAS ROSWELL, NEW MEXICO U.S. GEOLOGICAL SURVEY ROSWELL, NEW MEXICO