

RECEIVED

Form 9-331

Dec 1983

OCT 12 1982

UNITED STATES

DEPARTMENT OF THE INTERIOR

GEOLOGICAL SURVEY

O. C. D.
ARTESIA, OFFICEN. OIL & GAS. COMMISSION
Drawer 82
Artesia, NM 88210Form Approved
Budget Bureau No. 42-R1424

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter or plug back to a different reservoir. Use Form 9-331-C for such proposals.

1. oil well ☐ gas well ☒ other ☐
2. NAME OF OPERATOR
Yates Petroleum Corporation ✓
3. ADDRESS OF OPERATOR
207 South 4th St., Artesia, NM 88210
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 660 FSL & 1980 FWL, Sec. 34-7S-25E
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

PULL OR ALTER CASING

MULTIPLE COMPLETE

CHANGE ZONES

ABANDON*

(other)

X
X

5. LEASE NM 2351
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Federal HY
9. WELL NO.
4
10. FIELD OR WILDCAT NAME
Pecos Slope Abo
11. SEC. T., R., M., OR BLK. AND SURVEY OR AREA
Unit N, Sec. 34-T7S-R25E
12. COUNTY OR PARISH 13. STATE
Chaves NM
14. API NO.
15. ELEVATIONS (SHOW DE, KDB, AND WD)
3554.3' GR

(NOTE: Report results of multiple completion or change of formation) SEP 22 1982

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.

TD 4100'. WOC 4-1/2" casing from 7-23-82 to 9-11-82. Tested to 1000 psi, released pressure, held okay. WIH and perforated 3668-3862' w/20 .40" holes as follows: 3668, 69, 70, 71, 3708, 13, 21, 22, 3845, 46, 47, 48, 53, 54, 55, 56, 59, 60, 61, 62'. WIH w/2-3/8" tubing, packer, RBP. Acidized 3668-3862' w/2500 gallons 7 1/2% acid. Pulled tubing, packer, RBP. Frac'd down casing w/40000 gallons gelled KCL water, 70000# 20/40 sand. Well stabilized at 250 psi on 1/2" choke = 1647 mcifpd.

Subsurface Safety Valve: Manu. and Type

Set @

Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED: [Signature] TITLE Engineering Secty DATE 9-20-82

ACCEPTED FOR RECORD

(ORIG. SGD.) DAVID R. GLASS

This space for Federal or State office use

APPROVED BY
CONDITIONS OF APPROVAL

OCT 8 1982

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

See Instructions on Reverse Side