NM OIL CONS. COMMISSIO Drawer DD	N
Form 9-331 rtesia, NM 88210	Form Approved.
Dec. 1973	Budget Bureau No. 42-R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	NM 10588
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT NAME
(Do not use this form for proposals to drill or to deepen or plug technic to the proposals.)	8. FARM OR LEASE NAME
1. oil	George QJ Federal
well □ gas well other JUN 1 1982	9. WELL NO.
2. NAME OF OPERATOR	6
Yates Petroleum Corporation ✓ O. C. D.	10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR	Pecos Slope Abo
207 South 4th St., Artesia, NM 88210	11. SEC., T., R., M., OR BLK. AND SURVEY OR
<ul> <li>4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)</li> <li>660 FNL &amp; 990 FWL, Sec. 26-6S-25E AT SURFACE:</li> <li>AT TOP PROD. INTERVAL:</li> <li>AT TOTAL DEPTH:</li> </ul>	AREA Unit D, Sec. 26-T6S-R25E 12. COUNTY OR PARISH 13. STATE Chaves NM 14. API NO.
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REPAIR WELL	AY 2 5 1982 (NOTE: Report results of multiple completion or zone OIL & Cychange on Form 9-330.) DECLOGICAL SURVEY VELL, NEV/ MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Spudded a 14-3/4" hole 2:00 PM 5-9-82. Set 40' of 20" conductor pipe. Ran 22 joints of 10-3/4" 40.5# ST&C casing at 886'. 1-Texas Pattern guide shoe at 886'. Flapper insert float at 846'. Cemented w/500 sacks Halliburton Lite, 1/4# flocele and 2% CaCl2. Tailed in w/200 sacks Class "C" 2% CaCl2. Compressive strength of cement - 1250 psi in 12 hours. PD 6:45 PM 5-10-82. Bumped plug to 750 psi, released pressure and float held okay. Cement circulated 40 sacks to pit. WOC. Drilled out 12:45 PM 5-11-82. WOC 18 hours. Nippled up and tested to 1000 psi, okay. Reduced hole to 7-7/8". Drilled plug and resumed drilling.

Г	ACCEPTED FOR RECORD
Subsurface Safety Valve: Manu. and Type	Ft.
18. I hereby certify that the foregoing is true and correct	MAT 21
SIGNEDAL anta bodien_ TITLE Engineering Secty	
(This space for Federal or State office use)	ROSWELL NEW MEXICUL
APPROVED BY TITLE	DATE

\*See Instructions on Reverse Side