

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

RECEIVED

JUN 30 1982

1. oil well ☐ gas well ☒ other ☐

2. NAME OF OPERATOR
Harper Oil Company

O. C. D.
ARTESIA, OFFICE

3. ADDRESS OF OPERATOR 73102
904 Hightower Bldg., Okla. City, OK

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 2310' FSL & 1880' FWL
AT TOP PROD. INTERVAL: Same
AT TOTAL DEPTH: *W.R.*

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) Set casing

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☐
☐
☐

RECEIVED
JUN 1 1982

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

4-23-82 Spudded @ 11:00 P.M.
4-25-82 Drilled to 390'. Set 13 3/8" csg. @ 390' w/400 sks cmt. WOC 24 hrs. Held okay.
4-30-82 Drilled to 1800'. Set 8 5/8" csg. @ 1800' w/900 sks cmt. WOC 24 hrs. Tested to 3000#, held okay.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED *[Signature]* TITLE Production Manager 5-25-82

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____ DATE _____

ACCEPTED FOR RECORD

*See Instructions on Reverse Side

JUN 29 1982
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

