

NO. OF COPIES RECEIVED	3
DISTRIBUTION	
SANTA FE	1
FILE	1
U.S.G.S.	
LAND OFFICE	
OPERATOR	1

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

RECEIVED

MAY 27 1982

SONDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A CEMENTED WELL. USE APPLICATION FOR PERMIT - (FORM C-103) FOR SUCH PROPOSALS.

O. C. D.
ARTESIA, OFFICE

OIL WELL ☐	GAS WELL ☒	OTHER ☐
Name of Operator Yates Petroleum Corporation ✓		
Address of Operator 207 South 4th St., Artesia, NM 88210		
Location of Well UNIT LETTER M FEET FROM THE South LINE AND 990 FEET FROM THE West LINE SECTION 10 TOWNSHIP 6S RANGE 26E		
15. Elevation (Show whether DF, RT, GS, etc.) 3625' GR		

5a. Indicate Type of Lease State ☐ For ☒
5. State Oil & Gas Lease No.
7. Unit Agreement No.
8. Farm or Lease Date Shadden TN
9. Well No. 1
10. Field and Pool, or adjacent Und. Pecos Slope Abo
12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☒	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☒	

1. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded 14-3/4" hole at 9:00 AM 5-22-82. Set 60' of 20" conductor pipe. Ran 23 jts of 10-3/4" 40.5# ST&C casing set at 926'. 1-Texas Pattern notched guide shoe set at 926'. Insert float at 886'. Cemented w/600 sacks Halliburton Lite, 1/4#/sack flocele and 2% CaCl₂. Tailed in w/200 sacks Class "C", 1/4#/sack flocele and 2% CaCl₂. Compressive strength of cement - 1250 psi in 12 hours. PD 3:25 PM 5-25-82. Bumped plug to 750 psi, released pressure and float held okay. Cement circulated 50 sacks. WOC. Drilled out 9:25 AM 5-25-82. WOC 18 hours. Nippled up and tested to 1000 psi, okay. Reduced hole to 9-7/8". Drilled plug and resumed drilling.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

CHIEF <i>[Signature]</i>	TITLE Engineering Secretary	DATE 5-26-82
PROVED BY <i>[Signature]</i>	TITLE OIL AND GAS INSPECTOR	DATE JUN 1 1982
CONDITIONS OF APPROVAL, IF ANY:		

