

NM OIL CONS. COMMISSION

Drawer DD

Artesia, NM 88210

UNITED STATES

DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

CISE

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☒ other

2. NAME OF OPERATOR
Yates Petroleum Corporation

3. ADDRESS OF OPERATOR
207 South 4th St., Artesia, NM 88210

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 660 FSL & FEL, Sec. 27-T5S-R24E
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐


MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) ☐

SUBSEQUENT REPORT ☒



OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

Form Approved.
Budget Bureau No. 42-R1424

5. LEASE

NM 14983

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

RECEIVED

7. UNIT AGREEMENT NAME

MAY - 7 1982

8. FARM OR LEASE NAME
Monaghan QY Federal

9. WELL NO.

5

10. FIELD OR WILDCAT NAME
Pecos Slope Abo

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Unit P, Sec. 27-T5S-R24E

12. COUNTY OR PARISH 13. STATE
Chaves NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3993.9' GR

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded 14-3/4" hole at 9:15 PM 4-26-82. Set 40' of 20" conductor pipe. Ran 22 joints of 10-3/4" 50.5# J-55 ST&C casing set at 883'. 1-Texas Pattern guide shoe at 883'. Insert float at 843'. Cemented w/500 sacks Halliburton Lite, 1/4#/sack flocele and 2% CaCl₂. Tailed in w/250 sacks Class "C" 2% CaCl₂. Compressive strenght of cement - 1250 psi in 12 hours. PD 11:10 PM 4-27-82. Bumped plug to 800 psi, released pressure and float held okay. WOC. Drilled out 5:10 AM 4-28-82. WOC 18 hours. Nippled up and tested to 1000 psi, okay. Reduced hole to 9-7/8". Drilled plug and resumed drilling.

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct

SIGNED: Walter D. Allen TITLE: Engineering Secty

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE

