

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

RECEIVED

MAY 21 1982

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back into a different reservoir. Use Form 9-331-C for such proposals.)

ARTESIA, OFFICE

1. oil ☐ gas ☒ other ☐

2. NAME OF OPERATOR

Yates Petroleum Corporation

3. ADDRESS OF OPERATOR

207 South 4th St., Artesia, NM 88210

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 660 FNL & FWL, Sec. 4-8S-26E

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) ☐

5. LEASE

NM 18607

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Rita TZ Federal

9. WELL NO.

1

10. FIELD OR WILDCAT NAME

Und. Abo

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Unit D, Sec. 4-T8S-R26E

12. COUNTY OR PARISH

Chaves

13. STATE

NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
3685.8' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded a 14-3/4" hole at 9:00 AM 4-29-82. Set 40' of 20" conductor pipe. Ran 25 joints of 10-3/4" 40.5# J-55 casing set at 1001'. 1-Texas Pattern guide shoe at 1001'. Insert float at 961'. Cemented w/600 sacks Halliburton Lite, 1/4# flocele and 2% CaCl₂. Tailed in w/200 sacks Class "C" 2% CaCl₂. PD 2:15 PM 5-2-82. Bumped plug to 750 psi, released pressure and float held okay. Cement circulated 50 sacks to pit. WOC. Drilled out 8:15 AM 5-3-82. WOC 18 hours. Nipped up and tested to 1000 psi, okay. Drilled plug and resumed drilling.

Subsurface Safety Valve: Manu. and Type

Set @

Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Engineering Secty

DATE

5-11-82

(This space for Federal or State office use)

ACCEPTED FOR RECORD

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

MAY 20 1982
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO