

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	/
FILE	/
U.S.G.S.	
LAND OFFICE	
OPERATOR	/

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPLICATION FOR PERMIT - (FORM C-101) FOR SUCH PROPOSALS.)

AUG 11 1982

OIL WELL ☐

GAS WELL ☒

OTHER-

Name of Operator

Yates Petroleum Corporation

O. C. D.

ARTESIA, OFFICE

Address of Operator

207 South 4th St., Artesia, NM 88210

Location of Well

UNIT LETTER A 660 FEET FROM THE North LINE AND 660 FEET FROM

THE East LINE, SECTION 3 TOWNSHIP 8S RANGE 26E N.M.P.M.

15. Elevation (Show whether DF, RT, CR, etc.)

3788' GR

5a. Indicate Type of Lease

State ☐

Fee ☒

5. State Oil & Gas Lease No.

7. Unit Agreement Name

8. Name of Lease Name

Cornett TI

9. Well No.

1

10. Field and Pool, or Wildcat

Und. ~~Recess~~ Slope Abo

12. County

Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

TEMPORARILY ABANDON ☐

PULL OR ALTER CASING ☐

OTHER ☐

PLUG AND ABANDON ☐

CHANGE PLANS ☐

REMEDIAL WORK ☐

COMMENCE DRILLING OPNS. ☒

CASING TEST AND CEMENT JOB ☒

OTHER ☐

ALTERING CASING ☐

PLUG AND ABANDONMENT ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded 14-3/4" hole 1:30 PM 8-4-82. Set 40' of 20" conductor pipe. Ran 25 joints of 10-3/4" 40.5# J-55 casing set at 996'. 1-Texas Pattern guide shoe set 996'. Flapper insert float 955'. Cemented w/500 sacks Pacesetter Lite and 3% CaCl. Tailed in w/300 sacks Class "C" 2% CaCl. Compressive strength of cement - 1250 psi in 12 hours. PD 1:30 AM 8-6-82. Bumped plug to 1000 psi, released pressure and float held okay. Cement circulated 25 sacks to pit. WOC.
Drilled out 7:30 PM 8-6-82. WOC 18 hours. Nippled up and tested to 1000 psi, okay. Reduced hole to 9-7/8". Drilled plug and resumed drilling.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED

TITLE Engineering Secretary

DATE 8-9-82

APPROVED BY

TITLE

SUPERVISOR, DISTRICT II

DATE

AUG 12 1982

CONDITIONS OF APPROVAL, IF ANY: