

Form 9-331
Dec. 1973

NM OIL CONS. COMMISSION
Drawer DD
Artesia, NM 88210

RECEIVED BY

NOV 09 1984

Form Approved.
Budget Bureau No. 42-R1424

UNITED STATES O. C. D.
DEPARTMENT OF THE INTERIOR ARTESIA, OFFICE
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☐ other ☐ P&A

2. NAME OF OPERATOR
Yates Petroleum Corporation

3. ADDRESS OF OPERATOR
207 South 4th St., Artesia, NM 88210

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1980 FNL & 660 FNL, Sec. 33-6S-24E
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
PULL OR ALTER CASING
MULTIPLE COMPLETE
CHANGE ZONES
ABANDON*
(other)

SUBSEQUENT REPORT OF:

5. LEASE

NM 29314

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Two Jacks TM Federal

9. WELL NO. 1

10. FIELD OR WILDCAT NAME
Pecos Slope Abo

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Unit H, Sec. 33-T6S-R24E

12. COUNTY OR PARISH 13. STATE
Chaves NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)
4014' GR

(NOTE: Report results of multiple completion or change of form 9-330.)

RECEIVED
MAY 27 1982

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 3950'. Well plugged and abandoned as follows:

Plug #1: 50 sacks Class "C" 3% CaCl₂. Plug set 3410'. PD 2:00 AM 5-18-82.
Waited 4 hrs. Could not tag cement. 14 joints drill pipe cemented.
Pumped a 2nd plug and lost returns. Pumped 10 sacks Thixoment. Pumped another 10 sacks Thixoment. PD 1:00 AM 5-18-82. Pumped 75 sacks of Thixom
Plug #2: 50 sacks Class "C" 3% CaCl₂. Plug set 1660'. Lost returns and pumped 30 sacks Thixoment. PD 3:00 AM 5-19-82. Got returns back.
Plug #3: 60 sacks Class "C" 3% CaCl₂. Plug set at surface. PD 7:25 AM 5-19-82.
Circulated 15 sacks.
Dry hole marker will be installed. Surface will be restored in accordance with USGS-BLM requirements. Verbal approval of plugging given by Mr. James Gillham USGS, Roswell, May 17, 1982.

Subsurface Safety Valve: Manu. and Type

Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Peter W. Chester TITLE Engineering Secty DATE 5-24-82

APPROVED (This space for Federal or State office use)

(Orig. Sgd.) PETER W. CHESTER

CONDITIONS OF APPROVAL, IF ANY:

NOV 7 1984