

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

RECEIVED

1. oil ☐ gas ☒ well other

2. NAME OF OPERATOR

Yates Petroleum Corporation

3. ADDRESS OF OPERATOR

207 South 4th St., Artesia, NM, 88210

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 1980 FSL & 1980 FWL, Sec. 4-7S-26E

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) Production Casing, Perforate, Treat

5. LEASE

NM 27916

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

North Sturgeon PR Federal

9. WELL NO.

2

10. FIELD OR WILDCAT NAME

Pecos Slope Abo

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Unit K, Sec. 4-T7S-R26E

12. COUNTY OR PARISH

Chaves

13. STATE

NM

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

3629' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

TD 4360'. Ran 93 joints of 4-1/2" 10.5# J-55 casing set at 4360'. 1-regular guide shoe at 4360'. Float collar at 4317'. Cemented w/375 sacks 50/50 Poz, 2% gel, 2# KCL, .3% Halad-4 and .3% CFR-2. Compressive strength of cement - 1050 psi in 12 hours. PD 3:00 AM 5-31-82. Bumped plug to 1000 psi, released pressure and float held okay. WOC. WIH and perforated 4014-4277' w/15 .50" holes as follows: 4014, 15, 16, 17, 4180, 81, 82, 83, 84, 4272, 73, 74, 75, 76 and 77'. Acidized perforations 4014-4277 w/2000 gallons 7-1/2% NE acid. Sand frac'd perforations 4014-4277 (via casing) w/40000 gallons gelled KCL water and 63000 20/40 sand.

Subsurface Safety Valve: Manu. and Type

Set @ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Robert D. Smith TITLE Engineering Secty DATE 7-7-82

ACCEPTED FOR RECORD

(This space for Federal or State office use)

APPROVED BY
CONDITIONS OF APPROVAL

TITLE DATE

OCT 15 1982

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side

RECEIVED
JUL 9 1982