

NM Oil
Drawer DD
Artesia, NM 88210

Form Approved.
Budget Bureau No. 42-R1424

SF/John

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or to change the location of a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ well gas ☒ well other ☐

JUN 30 1982

2. NAME OF OPERATOR

Yates Petroleum Corporation

O. C. D.

3. ADDRESS OF OPERATOR

ARTESIA, OFFICE

207 South 4th St., Artesia, NM 88210

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE: 660 FSL & 1980 FWL, Sec. 15-6S-25E

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☐

(other) ☐

☒

☐

☐

☐

☐

☐

☐

☐

☐

5. LEASE

NM-10263

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Thomas LN Federal

9. WELL NO.

6

10. FIELD OR WILDCAT NAME

Pecos Slope Abo

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Unit N, Sec. 15-T6S-R25E

12. COUNTY OR PARISH

Chaves

13. STATE

NM

14. API NO.

15. ELEVATIONS (SHOW DE, KDB, AND WD)

3916.75 CR

DELIVERED
JUN 14 1982

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded a 14-3/4" hole 8:00 PM 6-3-82. Set 40' of 20" conductor pipe. Ran 23 joints of 10-3/4" 40.5# J-55 casing set 919'. 1-notched guide shoe at 919'. Auto-fill insert float at 881'. Cemented w/350 sacks Pacesetter Lite 3% CaCl₂. Tailed in w/300 sacks Class "C" and 2% CaCl. Compressive strength of cement - 1250 psi in 12 hours. PD 2:40 AM 6-7-82. Bumped plug to 800 psi, released pressure and float held okay. Cement circulated 50 sacks to pit. WOC. Drilled out 8:45 PM 6-7-82. WOC 18 hours. Nipped up and tested to 1000 psi, okay. Reduced hole to 7-7/8". Drilled plug and resumed drilling.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED John L. Smith TITLE Engineering Secty DATE 6-10-82

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD

JUN 29 1982
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO