

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug a well to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other ☐ **Oil & Gas**
MINERALS MGMT. SERVICE
ROSWELL, NEW MEXICO
2. NAME OF OPERATOR
Yates Petroleum Corporation
3. ADDRESS OF OPERATOR
207 South 4th St., Artesia, NM 88210
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 660 FSL & 660 FWL, Sec. 18-8S-26E
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

- | REQUEST FOR APPROVAL TO: | SUBSEQUENT REPORT OF: |
|---|-------------------------------------|
| TEST WATER SHUT-OFF <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| FRACTURE TREAT <input type="checkbox"/> | <input type="checkbox"/> |
| SHOOT OR ACIDIZE <input type="checkbox"/> | <input type="checkbox"/> |
| REPAIR WELL <input type="checkbox"/> | <input type="checkbox"/> |
| PULL OR ALTER CASING <input type="checkbox"/> | <input type="checkbox"/> |
| MULTIPLE COMPLETE <input type="checkbox"/> | <input type="checkbox"/> |
| CHANGE ZONES <input type="checkbox"/> | <input type="checkbox"/> |
| ABANDON* <input type="checkbox"/> | <input type="checkbox"/> |
| (other) | |

5. LEASE
NM 18031
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
RECEIVED
8. FARM OR LEASE NAME
Huckaby TJ Federal
9. WELL NO.
1 **OCT 26 1982**
10. FIELD OR WILDCAT NAME
Und. Pecos Slope Abn **O. C. D. ARTESIA, OFFICE**
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Unit M, Sec. 18-T8S-R26E
12. COUNTY OR PARISH Chaves 13. STATE NM
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
3583.3' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded a 14-3/4" hole 8:30 AM 10-5-82. Ran 921 joints of 10-3/4" 40.5# J-55 casing set at 921'. 1-Texas Pattern notched guide shoe set at 921'. Regular insert float set at 881'. Cemented w/400 sacks Pacesetter Lite, 1/4# celloseal, 2% CaCl₂. Tailed in w/300 sacks Class "C" 2% CaCl₂. Compressive strength of cement - 1250 psi in 12 hours. PD 5:45 AM 10-7-82. Bumped plug to 1000 psi, released pressure and float did not hold. Cement circulated 35 sacks to pit. WOC. Drilled out 12:30 AM 10-8-82. WOC 18 hours and 45 minutes. Nippled up and tested to 1000 psi, okay. Reduced hole to 9-7/8". Drilled plug and resumed drilling.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED David R. Glass TITLE Engineering Secty DATE 10-19-82

APPROVED BY _____ (This space for Federal or State office use)
CONDITIONS OF APPROVAL _____ TITLE _____ DATE _____

ACCEPTED FOR RECORD
(ORIG. SGD.) **DAVID R. GLASS**
OCT 25 1982
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side