ABANDON*

(other) Spud well.

NM OIL CONS. COMMISSION

Form Approved.

Budget Bureau No. 42-R1424

.....

100

LINITED STATES

Artesia, NN 882105 LEASE

0111.25 0111.20	-3. L	۲.
DEPARTMENT OF THE INTERIOR		
GEOLOGICAL SURVEY	6. IF	=


GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE	OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill that deepen or plug back to a different reservoir. Use Form 9–331–C for such propolals.) RECEIVED	7. UNIT AGREEMENT NAME	
1. oil gas Well other 2. NAME OF OPERATOR Yates Petroleum Corporation 3. ADDRESS OF OPERATOR 207 South 4th St., Artesia, ARTES 82 PF5 CE 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)	8. FARM OR LEASE NAME Adell UJ Federal 9. WELL NO. 1 10. FIELD OR WILDCAT NAME Wildcat Abo. 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Unit A, Sec. 7-T10S-R25E	
AT SURFACE:660 FNL 660 FEL, Sec. 7-10S-25E AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	12. COUNTY OR PARISH Chaves 14. API NO.	13. STATE NM
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	15. ELEVATIONS (SHOW DF, KDB, AND WD) 3542.5' GR	
TECT WATER CHUT OF		

gas 1. oil X well [_] well SEP 3 or 1982 2. NAME OF OPERATOR Yates Petroleum Corporation 6. C. D. 3. ADDRESS OF OPERATOR 207 South 4th St., Artesia, ANT 88216 CE 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space AT SURFACE: 660 FNL 660 FEL, Sec. 7-10S-25E AT TOP PROD. INTERVAL: AT TOTAL DEPTH: 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTIC REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates. including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Spudded well with Artesia Fishing Tool rotary rig 12:00 noon 6-30-82.



	13. 66 3. 62 62 62 62 62 62 62 62 62 62 62 62 62
Subsurface Safety Valve: Manu. and Type	Set @ Ft.
18. I hereby certify that the foregoing is true a	and correct
SIGNED LOCKED FOR RECORD	TITLE Engineering Secty DATE 6-30-82
	is space for Federal or State office use)
APPROVED BY	TITLE
CCNDITIONS OF APTRET 2 9 1982	
U.S. GEOLOGICAL SURVEY	
ROSWELL, NEW MEXICO	*See Instructions on Reverse Side