Form 9-331 Dec. 1973 UNITED STATES DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	B8210 5. LEASE
DEPARTMENT OF THE INTERIOR	NN 16073 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9–331–C for such proposals.)	7. UNIT AGREEMENT NAME
 oil well gas well other OCT 5 1982 NAME OF OPERATOR OC. D. Yates Petroleum Corporation ARTESIA, OFFICE ADDRESS OF OPERATOR ARTESIA, OFFICE 207 South 4th St., Artesia, NM 88210 LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.) AT SURFACE: 1980 FSL 1980 FWL, Sec. 15-9S-25E AT TOP PROD. INTERVAL: 	Sarah UM Federal 9. WELL NO. 1 10. FIELD OR WILDCAT NAME Wildcat Abo 11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Unit K, Sec. 15-T9S-R25E 12. COUNTY OR PARISH Chaves NM
AT TOTAL DEPTH: UM. N 16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF: TEST WATER SHUT-OFF FRACTURE TREAT SHOOT- OR ACIDIZE REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other] Spud well	 14. API NO. 15. ELEVATIONS (SHOW DF, KDB, AND WD) 3506.5' GR (NOTE: Report results of multiple completion or zone change on Form 9–330.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly statincluding estimated date of starting any proposed work. If well is measured and true vertical depths for all markers and zones pertine. Spudded a 14-3/4" hole at 2:00 PM 6-30-82. pipe and 80' of 20" conductor pipe.	directionally drilled, give subsurface locations and ent to this work.)*

1

-

Subsurface Safety Valve: Manu. and Type		Set @	0 Ft.
	and correct	date <u>7-1-82</u>	
ACCEPTED FOR RECORD (T APPROVED BY CONDITIONS OF APPROVAL, IF ANY: OCT 4 1982	his space for Federal or State office us		
U.S. GEOLOGICAL SURVE ROSWELL, NEW MEXICO	Y See instructions on Reverse Side		

.