

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to develop a well back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☒ other ☐ OCT 18 1982
2. NAME OF OPERATOR MESA PETROLEUM CO. O. C. D.
3. ADDRESS OF OPERATOR ARTESIA, OFFICE
1000 VAUGHN BUILDING/MIDLAND TX 79701-4493
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 2310' FSL & 990' FEL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH: SAME

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) TD, 7 7/8" csg & cmt

SUBSEQUENT REPORT OF:

RECEIVED
JUL 2 1982

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Drilled 7 7/8" hole to TD of 3139' on 6-29-82. Ran 73 jts 4 1/2", 10.5#, K-55 casing set at 3003'. Pumped 150 bbls 3% KCL water + 20 bbls acid flush and cemented with 350 sxs Class "C" + 5#/sx KCL + 3/10% Halad-4 + 2/10% CFR-2. PD at 12:30 PM, 6-30-82. Cement did not circulate. Released rig at 6:00 PM, 6-30-82. WOCU.

XC: MMS (7), TLS, CEN RCDS, ACCTG, MEC, ROSWELL, REM, FILE, (PARTNERS)

Subsurface Safety Valve: Manu. and Type

18. I hereby certify that the foregoing is true and correct.

SIGNED A. Arnold Hall TITLE PETROLEUM ENGINEER DATE 7-01-82

APPROVED BY DAVID R. GLASS (ORIG. SGD.) TITLE DATE

CONDITIONS OF APPROVAL IF ANY: OCT 15 1982

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

See Instructions on Reverse Side