

OIL CONSERVATION DIVISION

P. O. BOX 2086

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.G.S.	<input checked="" type="checkbox"/>
LAND OFFICE	<input checked="" type="checkbox"/>
OPERATOR	<input checked="" type="checkbox"/>

RECEIVED

JAN 07 1983

O. C. D.

5a. Indicate Type of Lease

State ☐Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

ARTESIA, OFFICE

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)OIL
WELL ☐GAS
WELL ☒

OTHER-

Name of Operator

Yates Petroleum Corporation ✓

Address of Operator

207 South 4th St., Artesia, NM 88210

Location of Well

UNIT LETTER L, 1980 FEET FROM THE South LINE AND 660 FEET FROM

THE West LINE, SECTION 9 TOWNSHIP 6S RANGE 26E NMPM.

7. Unit Agreement Name

8. Farm or Lease Name

Caudill RZ

9. Well No.

3

10. Field and Pool, or Wildcat

Pecos Slope Abo

11. Elevation (Show whether DF, RT, GR, etc.)

3639' GR

12. County

Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐TEMPORARILY ABANDON ☐FULL OR ALTER CASING ☐PLUG AND ABANDON ☐CHANGE PLANS ☐OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐COMMENCE DRILLING OPNS. ☒CASING TEST AND CEMENT JOBS ☒OTHER ☐ALTERING CASING ☐PLUG AND ABANDONMENT ☐

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1105.

Spudded a 14-3/4" hole at 6:15 PM 1-1-83. Set 50' of 20" conductor pipe. Ran 31 jts of 10-3/4" 40.5# J-55 casing set at 949'. 1-Texas Pattern notched guide shoe set at 949'. Insert float set at 906'. Cemented w/400 sacks Pacsetter Lite, 3% CaCl₂, 1/4# celloseal. Tailed in w/300 sacks Class "C" 2% CaCl₂. Compressive strength of cement - 1250 psi in 12 hrs. PD 2:30 PM 1-3-83. Bumped plug to 1000 psi, released pressure and float held okay. Cement circulated 25 sacks. WOC. Drilled out 8:30 AM 1-4-83. WOC 18 hours. Nipped up and tested to 1000 psi for 30 minutes, okay. Reduced hole to 7-7/8". Drilled plug and resumed drilling.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Larry L. BrooksTITLE Production SupervisorDATE 1-5-83

Larry L. Brooks

Geologist

APPROVED BY _____

TITLE _____

DATE 1/10/83CONDITIONS OF APPROVAL: NMOC DIST. II