

UNITED STATES Artesia, NM 88210
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

RECEIVED

1. oil ☐ gas ☒ other ☐

2. NAME OF OPERATOR
MESA PETROLEUM CO.

3. ADDRESS OF OPERATOR
1000 VAUGHN BUILDING/MIDLAND, TX 79701-4293

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
850' FNL & 850' FWL

AT SURFACE:
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH: SAME

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐
(other) TD, 4 1/2" csg & cmt

☐
☐
☐
☐
☐
☐
☐
☐

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Drilled 7 7/8" hole to TD of 3215' on 7-23-82 with air. Ran 99 lbs 4 1/2", 10.5#, K-55 casing set at 3060'. Cemented with 350 sxs Class "C" + 5#/sxs KCL + 3/10% Halad-4 + 2/10% CFR-2. PD at 2:30 AM, 7-25-82. Cement did not circulate. Released rig at 6:00 AM, 7-25-82. WOCU.

XC: MMS (7), TLS, CEN RCDS, ACCTG, MEC, ROSWELL, REM, FILE, (PARTNERS)

Subsurface Safety Valve: Manu. and Type _____

18. I hereby certify that the foregoing is true and correct

SIGNED DAVID R. GLASS TITLE REGULATORY COORDINATOR DATE 7-27-82

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

OCT 15 1982

U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

*See Instructions on Reverse Side

OIL & GAS
U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO

RECEIVED
JUL 29 1982