

NEW MEXICO OIL CONSERVATION COMMISSION
DRAWER DD
ARTESIA, NEW MEXICO

FIELD REPORT FOR CEMENTING OF WELLS

Operator <u>Wallace Oil + Gas Co.</u>		Lease <u>Payton</u>		Well # <u>1</u>	
Location of Well	Unit <u>J</u>	Section <u>8</u>	Township <u>11S</u>	Range <u>25E</u>	County <u>Chaves</u>
Drilling Contractor	<u>Tex - Mex Drilg. Co.</u>		Type of Equipment <u>Rotary</u>		
* <u>Witness</u> <u>APPROVED CASING PROGRAM</u>					
Size of Hole	Size of Casing	Weight Per Foot	New or Used	Depth	Sacks Cement
<u>15 1/4"</u>	<u>13 3/8"</u>	<u>48 #</u>		<u>450</u>	<u>420</u>
* <u>12 1/4"</u>	<u>8 5/8"</u>	<u>24 #</u>		<u>1200</u>	<u>750</u>
<u>7 7/8"</u>	<u>4 1/2"</u>	<u>10.5 #</u>		<u>4500</u>	<u>250</u>
Casing Data:					
Surface _____ joints of _____ inch _____ # Grade _____					
(Approved) (Rejected) _____					
Inspected by _____ date _____					
Cementing Program					
Size of hole <u>12 1/4"</u> Size of Casing <u>8 5/8"</u> Sacks cement required _____					
Type of Shoe used <u>guide</u> Float collar used <u>insert</u> Btm 3 jts welded <u>yes</u>					
TD of hole <u>1245'</u> Set <u>1245'</u> Feet of <u>8 5/8"</u> Inch <u>24</u> # Grade <u>J-55</u>					
<u>New</u> -used csg. @ <u>1245'</u> with <u>250</u> sacks neat cement around shoe					
+ <u>450</u> sax <u>Western Site</u> additives _____					
Plug down @ <u>10900</u> (AM) (PM) Date <u>8/17/82</u>					
Cement circulated <u>No</u> No. of Sacks - <u>0</u>					
Cemented by <u>Western Co.</u> Witnessed by <u>Mike Stull</u>					
Temp. Survey ran @ <u>4300</u> (AM) (PM) Date <u>8/18/82</u> top cement @ <u>200'</u>					
Casing test @ _____ (AM) (PM) Date _____					
Method Used _____ Witnessed by _____					
Checked for shut off @ _____ (AM) (PM) Date _____					
Method used _____ Witnessed by _____					
Remarks: _____					

centrifuges <u>1205'-1005'-765'</u> 95% returns @ TD					

1. Run 1" + Tagged To c @ 200'
Pumped 106 sk c
Cement circulated To surface.