

OIL CONSERVATION DIVISIO.
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	<input checked="" type="checkbox"/>
FILE	<input checked="" type="checkbox"/>
U.S.O.B.	
LAND OFFICE	
OPERATOR	<input checked="" type="checkbox"/>

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L-6779

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	RECEIVED DEC 10 1982 O. C. D. ARTESIA, OFFICE 660	7. Unit Agreement Name
2. Name of Operator Yates Petroleum Corporation ✓		8. Farm or Lease Name Long Arroyo OD Com
3. Address of Operator 207 South 4th St., Artesia, NM 88210		9. Well No. 2
4. Location of Well UNIT LETTER <u>L</u> 1980 FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>14</u> TOWNSHIP <u>14S</u> RANGE <u>27E</u> NMPM.		10. Field and Pool, or Wildcat Und. Springer Basin Morrow
15. Elevation (Show whether DF, RT, GR, etc.) 3436.9' GR		12. County Chaves

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> Perforate <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 8100'. Ran Vannsystem to perforate 7755-72' w/68 .50" holes (4 SPF).
Well flowed at 580 psi on 1/2" choke = 3713 mcfpd.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>J. Santana G. O. de la Cruz</u>	TITLE <u>Production Supervisor</u>	DATE <u>12-10-82</u>
APPROVED BY <u>Mike Williams</u>	TITLE <u>OIL AND GAS INSPECTOR</u>	DATE <u>DEC 27 1982</u>
CONDITIONS OF APPROVAL, IF ANY:		