

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.B.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088

RECEIVED

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

SEP 9 1982

O. C. D.

ARTESIA, OFFICE

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒

GAS WELL ☐

OTHER ☐

Name of Operator

Yates Petroleum Corporation

Address of Operator

207 South 4th St., Artesia, NM 88210

Location of Well

UNIT LETTER F 2310 FEET FROM THE North LINE AND 1650 FEET FROM THE West LINE, SECTION 7 TOWNSHIP 8S RANGE 27E NEIGH.

15. Elevation (Show whether DF, RT, GR, etc.)

4027' GR

5. Indicate Type of Lease

State ☒

Fed ☐

6. State Oil & Gas Lease No.

V-133

7. Unit Agreement Name

8. Farm or Lease Name

Faircloth "VD" State

9. Well No.

1

10. Field and Pool, or Wildcat

Acme SA

12. County

Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

COMMENCE DRILLING OPNS. ☒

PLUG AND ABANDONMENT ☐

REPAIR OR ALTER CASING ☐

CHANGE PLANS ☐

CASING TEST AND CEMENT JOBS ☒

OTHER ☐

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded 14-3/4" hole 2:30 PM 9-4-82. Ran 9 joints of 10-3/4" 40.5# J-55 casing set 360'. 1-Texas Pattern guide shoe set 360'. Auto-fill insert float set 320'. Cemented w/125 sacks Halliburton Lite with 3% CaCl2, 1/4# flocele. Tailed in with 150 sacks Class "C" with 2% CaCl2. Compressive strength of cement - 1250 psi in 12 hours. PD 7:15 AM 9-5-82. Bumped plug to 1000 psi, released pressure and float held okay. Cement circulated 25 sacks. WOC. Drilled out 1:15 AM 9-6-82. WOC 18 hours. Nippled up and tested to 1000 psi, okay. Reduced hole to 7-7/8". Drilled plug and resumed drilling.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Lynette Goodlett

TITLE Engineering Secretary

DATE 9-9-82

APPROVED BY Leslie A. Clements

TITLE SUPERVISOR, DISTRICT II

DATE SEP 13 1982

CONDITIONS OF APPROVAL, IF ANY: