RECEIVED BY	9/EF
May 1963) UNITED STATES SUBMIT IN TRIPLICATES	Form approved.
JUL 11 198 DEPARTMENT OF THE INTERIOR (Other instructions on re-	Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.
GEOLOGICAL SURVEY	NM 21489
O. SUNDRY NOTICES AND REPORTS ON WELLS (TARTESIA: Bills form for papers to deill or to deepen or plug back to a different reservoir. Ose "APPLICATION FOR PERMIT—" for such proposals.)	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
1. OIL GAS G	7. UNIT AGREEMENT NAME
WELL WELL SOTHER 2. NAME OF OPERATOR	
Yates Petroleum Corporation	8. FARM OR LEASE NAME
3. ADDRESS OF OPERATOR	Comanche Hills "ZU" Fed.
207 South 4th St., Artesia, NM 88210	1
4. LOCATION OF WELL (Report location clearly and in accordance with any State organization of See also space 17 below.) At surface	10. FIELD AND POOL, OR WILDCAT
	Und. Pecos Slope Abo
660 FSL & 1980 FWL, Sec. 25-10S-25E JUL 9 1984	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, CED)	Unit N, Sec. 25-T10S-R25E 12. COUNTY OR PARISH 13. STATE
3712' GR	Chaves NM
Check Appropriate Box To Indicate Nature of Notice, Report, or C	
NOTICE OF INTENDION TO:	INT REPORT OF:
TEST WATER SHUT-OFF	The report of:
FRACTURE TREAT MULTIPLE COMPLETE FRACTURE TREATMENT	REPAIRING WELL
SHOOT OR ACIDIZE ABANDON* SHOOTING OR ACIDIZING	ALTERING CASING ABANDONMENT*
REPAIR WELL CHANGE PLANS (Other)	
(Other) (Note: Report results Completion or Recomple	of multiple completion on Well etion Report and Log form.)
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical nent to this work.)	including estimated date of starting any depths for all markers and zones perti-
Spudded 26" hole 12:15 PM 6-29-84 with rat hole. Set 401 of 2011 t	
diffing 14-5/4 note with rotary tools 3:00 PM /-2-84. Rap 21 itc.	f 10 2/4!! 40 5# + 55
casing set 303 . I-lexas rattern notched guide shoe set 909' Theore	floor sor 0661
Cemented w/475 sacks Pacesetter Lite with 3% CaCl2. Tailed in w/200 CaCl2. Compressive strength of compressive in 1250 rai in	sacks Class "C" 2%
CaCl2. Compressive strength of cement - 1250 psi in 12 hours. PD 8:1 plug to 1000 psi, released pressure and float held okay. Cement circ	1 . 1 /0 : 1
brilled out 2:45 Am /-5-84. WOU 18 hours and 30 minutes. MII and too	tod to 1000 4 f
30 minutes, OK. Reduced hole to 7-7/8". Drilled plug and resumed dr	illing.
	·
	e. *
	•
/)	
18. I hereby certify that the foregoing is true and correct	
SIGNED (Civile TITLE Production Supervisor	
(This space for Federal or State office use)	_ DATE
PETER W. CHESTER	_
CONDITIONS OF APPROVAL, IF ANY 1984	DATE

See Instructions on Reverse Side