

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Santa Fe	
M	
Land Office	
9 of M	
Operator	

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-005-62703

5. Indicate Type of Lease

STATE ☒

FEE ☐

6. State Oil & Gas Lease No.  
LG-6684

7. Lease Name or Unit Agreement Name

Trellis AGP State

8. Well No.

1

9. Pool name or Wildcat

Under:  
West Pecos Slope Abo

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL  
WELL ☐

GAS  
WELL ☒

OTHER

2. Name of Operator

YATES PETROLEUM CORPORATION

3. Address of Operator

105 South 4th St., Artesia, NM 88210

4. Well Location

Unit Letter I : 1980 Feet From The South Line and 660 Feet From The East Line

Section 16

Township

8S

Range

23E

NMPM

Chaves

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3967.5' GR

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☒

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded 26" hole 4:10 PM 5-29-89. Set 35' of 20" conductor. Resumed drilling 12 1/4" hole 9:00 PM 5-31-89. Lost circulation at 60'. Twisted off 340'. Attempted to run 8-5/8" casing, would not go past 617'. Worked and reamed to 368'. Set cement plug as follows: Plug #1 - set 368' w/100 sx Cl C w/3% CaCl. PD 4:30 PM 6-4-89. WOC 3 hrs. Tag cement 348'. Plug #2 - set 348' w/100 sx Cl C w/3% CaCl. PD 8:30 PM 6-4-89. WOC. Tag cement 340'. Reamed hole to 389'. Torque convertor leaking fluid. POOH to repair. Resumed drilling.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE Production Supervisor

DATE 6-9-89

TYPE OR PRINT NAME

Juanita Goodlett

TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY

MIKE WILLIAMS

SUPERVISOR, DISTRICT IV

APPROVED BY

TITLE

DATE

JUN 13 1989

CONDITIONS OF APPROVAL, IF ANY: