

+ c/sf  
dp

Form C-103  
Revised 1-1-89

State of New Mexico  
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

Submit 3 Copies  
to Appropriate  
District Office

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-005-62707
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. L-6772
7. Lease Name or Unit Agreement Name Whitworth RU State
8. Well No. 5
9. Pool name or Wildcat Undes. Four Ranch Wolfcamp

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

RECEIVED

JUL 20 '89

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER
2. Name of Operator YATES PETROLEUM CORPORATION
3. Address of Operator 105 South 4th St., Artesia, NM 88210
4. Well Location Unit Letter 0 : 660 Feet From The South Line and 1980 Feet From The East Line Section 12 Township 9S Range 26E NMPM Chaves County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3828.3' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data  
NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Spudded 26" hole with Frank's Rathole at 11:00 AM 7-11-89. Set 40' of 20" conductor. Redi-mix with 3-1/2 yards cement. Notified NMOC, Artesia, NM, of spud. Ran 28 joints 8-5/8" 24# J-55 ST&C casing set 1187'. Guide shoe set 1187', insert float set 1152'. Cemented w/450 sx Pacesetter Lite w/1/4#/sx Flocele, 5#/sx Gilsonite (yield 1.99, wt 12.4). Tailed in w/150 sx Class "C" + 2% CaCl2 (yield 1.32, wt 14.8). PD 10:15 PM 7-15-89. Bumped plug to 750 psi, released pressure and float held okay. Circulated 55 sacks to pit. WOC. Drilled out 12:30 PM 7-16-89. WOC 14 hours and 15 minutes. NU and tested to 1000 psi for 30 minutes. Reduced hole to 7-7/8". Drilled plug resumed drilling.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 7-18-89  
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

ORIGINAL SIGNED BY  
MIKE WILLIAMS

APPROVED BY SUPERVISOR, DISTRICT II DATE JUL 21 1989

CONDITIONS OF APPROVAL, IF ANY: