

- C. After abandonment of well, equipment will be removed, the location will be cleaned, and the pad and access road will be ripped, reseeded and returned to as near the original appearance as is possible.
- D. In the event of a producer, the land not necessary for production operations will be re-contoured and seeded with the recommended mixture submitted by the BLM.

11. Other Information:

A. Topography

The location is situated on a duned landform.

B. Soil

Typic Torripsamment subgroup.

C. Flora and Fauna

The vegetation cover consists of native range grasses with yucca plants, cactus and mesquite. Wild life in the area includes rabbits, dove, quail, and other inhabitants typical of semi-arid climate.

D. Ponds and Streams

Local drainage in this area is internal.

E. Residence and Structures

Ranch house approximately .6 mile to the east.

F. Archaeological, Historical and Cultural Sites

None observed in the area. The Archaeological Inspection Report is being forwarded by Archaeological Consultants, Inc.

G. Land Use

Grazing.

H. Surface Ownership

The proposed wellsite is on land owned by the Slash G Cattle Company of Roswell, New Mexico.

12. Operators Representative

Stanley L. Atnipp  
P. O. Box 552  
Midland, TX 79702  
(915) 682-1626



13. Certification

I hereby certify that I, or persons under my direct supervision, have inspected the proposed drillsite and access route; that I am familiar with the conditions which presently exist, that the statements made in this place are, to the best of my knowledge true and correct; and, that the work associated with the operations proposed herein will be performed by Marathon Oil Company and its contractors and subcontractors in conformity with this plan and the terms and conditions under which it is approved.

6/15/90  
Date

R.V. [Signature] for S.L.A.  
Marathon Oil Company