



PHONE (915) 673-7001 • 2111 BEECHWOOD • ABILENE, TX 79603

PHONE (505) 393-2326 • 101 E. MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR  
NEW MEXICO OCD  
ATTN: MIKE STUBBLEFIELD  
1301 GRAND AVE.  
ARTESIA, NM 88210  
FAX TO:


Receiving Date: 07/01/02  
Reporting Date: 07/03/02  
Project Owner: HANSON OP. CO.  
Project Name: HANLAD ST. #1 S.W.D  
Project Location: UNIT K, SEC16 T10S R27E

Sampling Date: 07/01/02  
Sample Type: SOIL  
Sample Condition: COOL & INTACT  
Sample Received By: AH  
Analyzed By: BC/AH


LAB NUMBER	SAMPLE ID	GRO (C <sub>6</sub> -C <sub>10</sub> ) (mg/Kg)	DRO (>C <sub>10</sub> -C <sub>28</sub> ) (mg/Kg)	Cl* (mg/Kg)
		07/02/02	07/02/02	07/03/02
H6857-1	PIT CLOSURE #1 EAST	<10.0	<10.0	1540
H6857-2	#2 SOUTH	<10.0	<10.0	576
H6857-3	#3 WEST	<10.0	<10.0	624
H6857-4	#4 NORTH	<10.0	<10.0	496
H6857-5	#5 MIDDLE	<10.0	<10.0	1870
Quality Control		802	744	1000
True Value QC		800	800	1000
% Recovery		100	93.0	100
Relative Percent Difference		2.2	2.1	4.0

METHODS: TPH GRO & DRO: EPA SW-846 8015 M; Cl: Std. Methods 4500-ClB

\*Analyses performed on 1:4 w:v aqueous extracts.

  
Chemist

7/3/02  
Date



H6857A.XLS

PLEASE NOTE: **Liability and Damages.** Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. All claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise.