

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

RECEIVED

APR 22 1991

WELL API NO. 30-005-62806	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No. V-3354	
7. Lease Name or Unit Agreement Name Quail State	
8. Well No. 1	
9. Pool name or Wildcat Pecos Slope Abo	

SUNDRY NOTICES AND REPORTS ON WELLS O. C. D.
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK OR A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	
2. Name of Operator Great Western Drilling Company	
3. Address of Operator P.O. Box 1659, Midland, TX 79702	
4. Well Location Unit Letter <u>A</u> : <u>660</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>36</u> Township <u>6-S</u> Range <u>24-E</u> NMPM <u>Chaves</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3,869.6' GR (3,878.6' RKB)</u>	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☒ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☒
OTHER: Same as page No. 1 ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Ran temperature survey, found top of cmt. on the outside @ 1,210' and inside @ 1,715'. Attempted to run 1", could not get below 110'.

04-11-91: Ran 3/4" TBG, could not get deeper than 566'. Got approval from OCD to cement @ 566'. Cemented w/175 Sxs. Class "C" + 2% CaCl₂, circulated 15 Sxs. good cement. Set 7-5/8" slips, nipples up BOP. Tested blind rams to 1,000 psi for 30 min.-held. TIH, tested pipe rams & Kelly cock to 1,000 psi for 30 Min.-held. Drilled out Cmt. & started drilling 6-1/2" hole @ 1,827'. Mr. Mike Williams w/OCD gave approval to cmt. @ 566' and Mr. Moore w/OCD witnessed.

04-12-91: Drlg. @ 2,720'. No problems last 24 hrs., topped salt section @ 1,980'.

- continued -

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M.B. Myers TITLE Asst. to Gen. Supt. DATE 04-19-91

TYPE OR PRINT NAME M.B. Myers TELEPHONE NO. (915) 682-524

(This space for State Use) ORIGINAL SIGNED BY
MIKE WILLIAMS
SUPERVISOR, DISTRICT II

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: