

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

c155
Form C-103
Revised March 25, 1999

WELL API NO. 30-005-62859
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: Witney Well No. 4 Pool name or Wildcat Chisum

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-103) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
Cibola Energy Corporation

3. Address of Operator
P.O. Box 1608, Albuquerque, NM 87103-1608

4. Well Location

Unit Letter P : 990 feet from the South line and 990 feet from the East line
Section 34 Township 10S Range 27E NMPM Chaves County

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
3765.3 GLE

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: Abandon Well Site ☒

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

An application to drill the subject well was filed June 20, 1991. Notice that the well was spudded was filed with the OCD on July 09, 1991 after the driller notified the office that the well had been spudded (a cable tool rig was being used). Subsequently, on the day the well was spudded, or on the following day, the driller notified the office that the rig had incurred a mechanical problem. It was determined that the time and cost related to repairing the rig made it impracticable to continue with the well. The effort was abandoned and the rig and related equipment was moved off location. The driller reported that the spudding operation had barely penetrated the earth before the rig broke down and that the hole made was covered up when the rig was removed from location. The well site was abandoned.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Harvey E. Yates Jr. TITLE President DATE 6/28/01
Type or print name By: Harvey E. Yates, Jr. for Cibola Energy Corporation Telephone No. (505) 242-2050
(This space for State use)

APPROVED BY [Signature] TITLE Wildcat DATE 1-3-02
Conditions of approval, if any: