| Submit 3 Copies to Appropriate | | State of New Mexico Energy, Minerals and Natural Resources Department | | Form C-103 Revised 1-1-89 | | | |
|--|--|--|--|--|---|--|--|
| District Office | OT CONSE | DVATTO | NDIVISION | | | | |
| <u>DISTRICT I</u> P.O. Box 1980, Hobbs, NM 8 | Box 1980, Hobbs, NM, 88240 | | | WELL API NO. | WELL API NO. 30–005–62931 | | |
| DISTRICT II P.O. Drawer DD, Artesia, NM | A 88210 Santa Fe, New Mexico 8 RECEIVED | | | 5. Indicate Type of | Lease | | |
| DISTRICT III | | erra (* 8. 1893) | | STATE FEE X | | | |
| 1000 Rio Brazos Rd., Aztec, N | IM 87410 | ۰. | | 6. State Oil & Gas | Lease No. | | |
| SUNI | ORY NOTICES AND REPOR | TS ON WEL | LOTER A SPENT | | /////////////////////////////////////// | | |
| (DO NOT USE THIS FOR DIFFER | M FOR PROPOSALS TO DRILL OI ENT RESERVOIR. USE "APPLICA (FORM C-101) FOR SUCH PROF | TION FOR PER | OR PLUG BACK TO A IMIT" | 7. Lease Name or U | Unit Agreement Name | | |
| 1. Type of Well: OIL WELL | | -TER | | Cannon XI | F | | |
| 2. Name of Operator YATES PETROLEUM CORPORATION 2. 1 | | | | | | | |
| 3. Address of Operator 9. Pool name or With the operator | | | | | 'ildcat | | |
| 105 South 4th St., Artesia, NM 88210 Pecos Slope | | | | | Abo | | |
| 4. Well Location | | North | ···· 661 | | m. Fact | | |
| Unit Letter | <u>1 : 1000</u> Feet From The | | Line and | | | Line | |
| Section 17 | Township 10S | | nge 25E | NMPM Chave | es | County | |
| | 10. Elevation | a (Show whether I 3520' GR | DF, RKB, RT, GR, etc.) | | | | |
| 11. | Check Appropriate Box | | | Report, or Other | Data | | |
| | E OF INTENTION TO: | | | BSEQUENT R | | | |
| PEFFORM REMEDIAL WO | | NDON | REMEDIAL WORK | | ALTERING CASING | | |
| TEMPORARILY ABANDON | — | s 🗆 | | | | | |
| PULL OR ALTER CASING | \square | | CASING TEST AND | | | | |
| DTHER: OTHER:Ran 7" casing | | | | | x | | |
| <pre>work) SEE RULE 1103. 12-30-92. Ran set 775'. Cem + 2% CaCl2 (yi held OK. Ceme 300'. Ran 1 " DV tool on 4-1 WOC 27 hours a</pre> | mpleted Operations (Clearly state all pe 20 joints 7" 23# J-5 ented w/100 sx Thixse eld 1.84, wt 1.32, wt nt did not circulate. . Cemented w/12 sx ' /2" string to cover 3 nd 35 minutes. Cut o ng. NOTE: Observed | 55 ST&C ca t and 200 14.8). WOC 6 h 'C" w/2% C 300'+ to off and we | sing set 813'. sx Halliburto PD 10:40 PM 12 ours. Ran Tem aC12. Circula surface. WOC. ld on flow nip | Guide shoe on Lite w/3% G 2-30-92. Bump pperature Surv ated 45 sacks Drilled out ople. Reduced | set 813'. Fl Granulite + 1# bed plug to 85 yey and found to cellar. W at 2:15 AM 1 hole to 6-1/ | Flocele D psi, FOC at ill run -1-93. 8" and rea | |
| | | | | | | | |
| I hereby certify that the information of the inform | tion above is trugand complete to the best o wtax and a dust Juanita Goodlett ORIGINAL SIGNED BY MIKE WILLIAMS | | belief. ne_Production | Supervisor | date1-7-9 telephone no. 50 JAN 1 2 | 5/748-1471 | |
| SIGNATURE | Juanita Goodlett | m | | Supervisor | DAIL | 5/748-1471 | |