

RECEIVED

YATES PETROLEUM CORPORATION
Salt Creek Unit #7
Section 21-T8S-R22E
Chaves County, New Mexico

Dec 1 6 42 AM '94

800
100

RESULTS OF DRILL STEM TESTS

DST #1 3514-3580': Misrun

DST #2 3514-3580' (Penn): TIMES: TO 15"; SI 60"; TO 60"; SI 120"; TO 60".
RECOVERY: 140' of gas cut mud. SAMPLER:).L CFG & 1750 cc mud. PRESSURES:
IHP 1877; IFP 73-50; ISIP 599; 2nd FP 56-76; 2nd SIP 1068; FFP 87-101; FHP 1893.