

Sheet No.

Anchor Test Daily Log Sheet



Tank Rental & Anchor Service Corp.

DATE	COMPANY	LEASE & WELL NO.	ANCHOR LOCATION	PULL PRESSURE LBS.	SEAL #	TEST O.K.	PULLED UP INCHES	EYE BROKE	ROD BROKE	UNABLE TO LOCATE	UNABLE TO TEST	SUCKER ROD PIPE CABLE	REMARKS	
													MANNER	REMARKS
5/27/1973	HALSON	288523A 1443	SE	18600	93266	✓							NEW	ANCHOR
		#4	SW	15600	98263	✓								(SEE ATTACHED)
			NW	9000	99304	✓								
			NE	19600	99260	✓								
		PATTERN	GERONIMO											
ART			SE											
			SW											
			NW											
			NE											
		PATTERN	GERONIMO											
ART			SE											
			SW											
			NW											
			NE											
		PATTERN	GERONIMO											
ART			SE											
			SW											
			NW											
			NE											
		PATTERN	GERONIMO											
ART			SE											
			SW											
			NW											
			NE											
		PATTERN	GERONIMO											
ART			SE											
			SW											
			NW											
			NE											
		PATTERN	GERONIMO											