

WELL TEST INTERPRETATION REPORT #:132188		PAGE: 2,
CLIENT : Thornton Operating Company		13-APR-94
REGION :CSD	SEQUENCE OF EVENTS	FIELD:Wildcat
DISTRICT:Midland		ZONE :Morrow
BASE :Hobbs N.M.		WELL :SM Fed #1
ENGINEER:Mark Luna		LOCATION:S6-13S-29E

DATE	TIME (HR:MIN)	DESCRIPTION	ET (MINS)	BHP (PSIA)	WHP (PSIG)
11-APR	17:17	Set Packers	-1		
	17:18	Start Flow on 1/8" Choke	0	44	.5"
	17:23	Weak Blow in H2O	5		4.25"
	17:28		10		9"H2O
	17:32	Bottom of Bucket	14		8 ozs
	17:33	End Flow & Start Shutin	15	46	8 ozs
	18:32	End Shutin	74	904	
	18:34	Start Flow on 1/8 Choke	76	52	88
	18:39	Good Blow Reading in PSI	81		2.0
	18:49		91		2.5
	19:04	Open on 1/4 Choke	106		2.5
	19:09	Surface Pressure Dropping	111		2.25
	19:33	End Flow & Start Shutin	135	54	1.0
	22:33	End Shutin	315	1957	
	22:40	Pulled Loose	322	4217	