YATES PETROLEUM CORPORATION Blackwater Unit #5 Section 4-T9S-R22E Chaves County, New Mexico

William State of

#32: ACID, SHOT, FRACTURE, CEMENT SQUEEZE, ETC.:

DEPTH 1	INTERVAL
---------	----------

TREATMENT

3534-3541'

Acidized with 1500 gallons 7-1/2% NEFE acid

and ball sealers

3350-33571

Acidized with 1500 gallons 7-1/2% NEFE acid

and ball sealers

Frac'd with 85000 gallons 35# crosslink gel and 210000# 20-40 Brady sand (down 5-1/2"

casing)