		- i	di
		l. ul Cons. Divi	ision (151
	P. A. 1	S 1 of Stroby	FORM APPROVED
		sia, NM 80210-28	dget Bureau No. 1004-0135
	T OF THE INTERIOR Arto AND MANAGEMENT	5. Lease	Designation and Serial No.
BUREAU OF I	AND MANAGEMENT		NM-11593
SUNDRY NOTICES	AND REPORTS ON WELLS		ian, Allottee or Tribe Name
Do not use this form for proposals to dr	Il or to deepen or reentry to a different	t reservoir.	
Use "APPLICATION FO	R PERMIT-" for such proposals		Distant
SURMIT	IN TRIPLICATE		it or CA, Agreement Designation
1. Type of Well	MAY	2 1 1997 8. Well 1	Name and No.
Oil Cass Well Other		Red	Rock NB_Federal #7
2. Name of Operator YATES PETROLEUM CORPORATION	(505) 748–1471)	ON DINAPIN	Vell No.
3. Address and Telephone No.			30-005-63103 and Pool, or Exploratory Area
105 South 4th St., Artesia,	NM 80210		
4. Location of Well (Footage, Sec., T., R., M., or Survey I	escription)	(CII) 11. Cou	Pecos Slope Abo
2310' FSL & 1300' FWL of Sec	tion 28-T6S-R25E (Unoit L, NW	SW)	
		(	Chaves Co., NM
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA			
TYPE OF ACTION			
TYPE OF SUBMISSION	IYPE		1 
Notice of Intent	Abandonment		Change of Plans
_	Recompletion		lew Construction Ion-Routine Fracturing
X Subsequent Report		<b>—</b>	Water Shut-Off
	Casing Repair		Conversion to Injection
Final Abandonment Notice	X Other Production	casing &	Dispose Water
	cement	Comp	Report results of multiple completion on Well letion or Recompletion Report and Log form )
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled,			
13. Describe Proposed or Completed Operations (Clearly state an permisen ocean), and give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)* TD 4000'. Reached TD at 9:30 AM 5-7-97. Ran 90 joints of 4-1/2" 10.5# J-55 (4000.50') TD 4000'. Reached TD at 9:30 AM 5-7-97. Ran 90 joints of 4-1/2" 10.5# J-55 (4000.50')			
TD 4000'. Reached TD at 9:30 AM 5-7-97. Kan 90 joints of 4 1/2 lots a 3955'. Bottom of casing set at 4000'. Float shoe set at 4000'. Float collar set at 3955'. Bottom			
to 750 psi for 1 minute, OK. Gement did not circulate. Woo. Refeased ing in the			
5-8-97. NOTE: Displaced with 2% KCL.			
· · · · · · · · · · · · · · · · · · ·	ACCEPTED FOR RECORD	ω	
Waiting on completion unit.	PEFER W. CHESTE		<b>a</b>
	i i i i i i i i i i i i i i i i i i i	Î Î Î	ר <del>ב</del> א
	MAY	BUREAU OF ROSWEL	E m
	MAY 1 9 1007		$\Xi \Omega$
	BUREAU OF LAND		CEIVI VIZ P
	BUREAU OF LAND MANAGE ROSWELL RESOURCE AR	MENT TE	ש ≤
			е п П
14. I hereby certify that the foregoing is true and correct		MENT FIC ME	0
Kut. AND	TideOperations Techn	ician 🗧	Date May 9, 1997
(This space for Federal of State office use)			
/	Tide		Date
Approved by Conditions of approval, if any:	t ine		

.

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.