

YATES PETROLEUM CORPORATION
Sacra SA #14
Section 19-T6S-R26E
Chaves County, New Mexico

#27: ACID, SHOT, FRACTURE, CEMENT, SQUEEZE, ETC.:

<u>DEPTH INTERVAL</u>	<u>TREATMENT</u>
5186-5192	Acidized with 600 gallons of 7-1/2% iron control HCL acid and ball sealers
5087-5095'	Acidized with 800 gallons of 7-1/2% iron control HCL acid and ball sealers
3796-4024'	Frac'd (down 4-1/2" casing) with 77000 gallons 65Q N2 foam and 159000# 16-30 Brady sand. Pumped 2000 gallons of 7-1/2% iron control HCL acid ahead of frac