

YATES PETROLEUM CORPORATION
Long Arroyo WH Federal #2
Section 11-T14S-R27E
Chaves County, New Mexico

RESULTS OF DRILL STEM TESTS:

DST #1 7636-7690' (Atoka): TIMES: TO 15"; SI 60"; TO 120"; SI 135". RECOVERY:
30' of drilling mud. SAMPLER: .11 cfg and 1100 cc mud. PRESSURES: IHP 3979;
IFP 69-45; ISIP 139; FFP 35-46; FSIP 1430; FHP 3979

DST #2 7895-7945' (Morrow): TIMES: TO 15"; SI 60"; TO 60"; SI 120". RECOVERY:
279' of gas cut mud. SAMPLER: .31 cfg and 1100 cc mud. PRESSURES: IHP 4059; IFP
83-100; ISIP 290; FFP 117-129; FSIP 2414; FHP 4068

