Submit 3 Copies To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources			Form C-103 Revised March 25, 1999			
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, winicials and Natural Resources			WELL API NO.			
District II	OIL CONSERVATION DIVISION			30-005-63420			
811 South First, Artesia, NM 88210 District III	1220 South St. Francis Dr.			5. Indicate Type of Lease			
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505			STATE X FEE 6. State Oil & Gas Lease No.			
1220 S. St. Francis Dr., Santa Fe, NM 87505	20 S. St. Francis Dr., Santa Fe, NM				LG-0563		
SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease	Name or	Unit Agreement Name:	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				Smernoff NL State			
PROPOSALS.)					off NL S	tate	
1. Type of Well:							
Oil Well Gas Well X Other 2. Name of Operator				7. Well	No		
Yates Petroleum Corporation				#7			
3. Address of Operator					8. Pool name or Wildcat		
105 S. 4th Street Artesia, NM 88210				Pecos Slope Abo			
4. Well Location			r _s				
TANK TO 1000 CAS A North II 1 1500 CAS A MONTH							
Unit Letter F: 1980 feet from the North line and 1500 feet from the West line							
Section 2	Township 5S	Range	24E 1	NMPM	Chav	es County	
betten =	10. Elevation (Show wh					oo aan	
3965' GR							
11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data							
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:							
PERFORM REMEDIAL WORK	PLUG AND ABANDON	PLUG AND ABANDON REMEDIAL WOR				ALTERING CASING [
TEMPORARILY ABANDON	CHANGE PLANS		DRILLING OPNS. PLUG AND ABANDONMENT				
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AT CEMENT JOB	ND			
OTHER:			OTHER: set and	cement pro	duction o	asing X	
Describe proposed or completed or	perations. (Clearly state al.	l pertine	L				
starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or							
recompilation.							
12/8/01 - Reached TD of 4075' at 2:30 PM.							
12/9/01 – Run open hole logs. Logger's TD 4076'. 12/10/01 – Ran 91 joints (4080.02') of casing set at 4075' as follows:							
12/10/01 – Ran 91 joints (4000.02) of casing set at 40/3 as follows. 17 joints 4-1/2" 10.5# SB (740.82')							
74 joints 4-1/2" 10.5# MV (3339.20')							
Float shoe set at 4075'. Float collar set at 4028.20'. Bottom marker set at 3334.18'.							
Cemented with 275 sxs Pecos Valley Lite + 3 pps D44 + 4 pps D24 + .1% D65 +.4% D167 + .2% D46 (yld 1.45, wt							
13). Plug down at 9:30 AM. Bumped plug to 1150 psi for 1 mins., held OK.							
Notified OCD before starting pipe.							
Rig released at 1:30 PM 12/10,	/01.						
I hereby certify that the information	above is true and complet	te to the	hest of my knowled	ge and helic			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.							
SIGNATURE ALLE TITLE Engineering Technician DATE December 20, 2001							
Type or print name Susan Herpin Telephone No. 505-748-1471							
(This space for State use)							
ADDROVED DV	STRICT II SUPERVISO	<i>ਜ਼ਿਸ਼ ਦ</i> ਿੱ ਨਿਲਾਨ	u u m			DATE DEC 2 8 2001	
APPPROVED BYConditions of approval, if any:		111LE			_	_DATE	