

Memo

From

L. A. HANSON
Oil & Gas Inspector

To

DeBaca County —

Sid Katy #1 Mabel Field
SW SW 13 - 1 N - 22 E.

Inspected 8-17-54

Pits are not filled, surface esg cut
of 4' below ground level, 24 cement plug
in top of esg. Pits & cellar are open.
Location is fenced.