

NEW MEXICO OIL CONSERVATION COMMISSION

P. O. DRAWER DD
ARTESIA, NEW MEXICO 88210

DATE 10-19-64

Diamond Shamrock

P.O. Box 400

Amarillo, Tx.

Gentlemen:

79188

Re: Plugging Reports

Form C-103, Report of Plugging for your Fields 26 1 D 26-IN-22E
Lease Well # Unit S-T-R

cannot be approved until a Division representative has made an inspection of the location and found it to be cleared to comply with Division Rules and Regulations. Please check each item in the space provided to indicate that the work has been done.

- (✓) 1. All pits have been filled and leveled.
- (✓) 2. Rat hole and cellar have been filled and leveled.
- (✓) 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete. It must show the quarter-quarter section or unit designation, section, township and range numbers which have been permanently stenciled or welded on the marker.
- (✓) 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- (✓) 5. The dead men and tie downs have been cut and removed.
- () 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk and equipment.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by filling in the blank form below and returning this letter to us so that our representative will not have to make more than one trip to the location.

OIL CONSERVATION DIVISION


Darryl Swift
DISTRICT GEOLOGIST

FILL IN BELOW AND RETURN

I certify that the above work has been done and the Fields
26 D 26-IN-22E is ready for your inspection and approval.

Well No. Unit S-T-R

William Elliott
Operator



RECEIVED
OCT 13 1964
FISCHER DEPT.